



Mary Meyer Certificate of Compliance

I. This certificate covers Mary Meyer item: MM 21617 Colonial Williamsburg Sally Baby Lamb

II. This product is certified to meet the following CPSC safety regulations:

ASTM F963 + 16 CFR 1500.3 (c) (6) (vi) Flammability Requirements
ASTM F963 + 16 CFR 1500 Physical and Mechanical Requirements
16 CFR 1303 Total Lead Content
ASTM F 963 Soluble Heavy Metal Content
Total Phthalates Content
Total Lead in Substrate per CPSIA 2008 (H.R. 4040)

III. This product was imported by:

Mary Meyer Corp.
Route 30
Townshend, VT 05353 USA
Tel (+852)-3580-0773

IV. Testing and compliance records are maintained by:

Hong Kong:
Mary Meyer (Hong Kong) Limited
11/F, Flat A, Siu On Commercial Building
243-245 Des Voeux Rd. West
Hong Kong, S.A.R. Peoples' Republic of China
Tel: (+852)-2915-2506
Email: compliance@marymeyer.com
Attn: Jeffrey Blauner

USA:
Mary Meyer Corp.
P.O. Box 275
Townshend, VT 05353
USA
Tel: (802)-365-7793
email: compliance@marymeyer.com
Attn: Vikki Dunn

V. This product was manufactured in:

Qingdao, Shandong Province, Peoples' Republic of China
September, 2009

VI. The product covered by this certificate was tested for compliance:

Hong Kong, S.A.R., Peoples' Republic of China
December, 2008

VII. Third party testing was conducted by:

Specialized Technology Resources (HK) Limited
16-17/F, Tower B, Regent Centre
63 Wo Yi Hop Road, Kwai Chung
New Territories, Hong Kong
S.A.R., Peoples' Republic of China
(+852)-2423-3092

Mary Meyer Corp.
P.O. Box 275, Route 30
Townshend, VT 05353 USA
Tel: (802)-365-7793 Fax: (802)-365-4233