



make mine mary meyer

Mary Meyer Certificate of Compliance

I. This certificate covers Mary Meyer item: MM 35200, Caterpillar rattle

II. This product is certified to meet the following CPSC safety regulations:

ASTM F963 + 16 CFR Flammability Test
16 CFR 1303 Total Lead Content
ASTM F963 + 16 CFR Physical and Mechanical Test
ASTM F 963 Soluble Heavy Metal Content
Total Lead in substrate per CPSIA 2008 (H.R. 4040)
Total Phthalates Content Test per CPSIA 2008 (H.R. 4040)

III. This product was imported by:

Mary Meyer Corp.
Route 30
Townshend, VT 05353 USA
Tel (+852)-3580-0773

IV. Testing and compliance records are maintained by:

Hong Kong:
Mary Meyer (Hong Kong) Limited
11/F, Flat A, Siu On Commercial Building
243-245 Des Voeux Rd. West
Hong Kong, S.A.R. Peoples' Republic of China
Tel: (+852)-2915-2506
Email: compliance@marymeyer.com
Attn: Jeffrey Blauner

USA:
Mary Meyer Corp.
P.O. Box 275
Townshend, VT 05353
USA
Tel: (802)-365-7793
email: compliance@marymeyer.com
Attn: Vikki Dunn

V. This product was manufactured in:

Dongguan, Guangdong Province, Peoples' Republic of China
May, 2009

VI. The product covered by this certificate was tested for compliance:

Guangzhou and Shenzhen, Guangdong Province, Peoples' Republic of China
September 2008 and April 2009

VII. Third party testing was conducted by:

Specialized Technology Resources (Shanghai) Ltd, Shenzhen Branch and Guangzhou Worldwide Standards and Testing Co., Ltd

2/F, 6/F, North Block, Wondial Building
#29, 6 South Keji Road
High Tech Industrial Park, Nanshan District, Shenzhen 518057
Guangdong Province, Peoples' Republic of China
(+86)-755-2601-8600

110 Dongguan Zhuang Rd., Tianhe District
Guangzhou, Guangdong Province
Peoples' Republic of China
(+86)-20-8723-6019

Mary Meyer Corp.
P.O. Box 275, Route 30
Townshend, VT 05353 USA
Tel: (802)-365-7793 Fax: (802)-365-4233