



make mine mary meyer

## Mary Meyer Certificate of Compliance

I. This certificate covers Mary Meyer item: MM 35200, Caterpillar rattle

II. This product is certified to meet the following CPSC safety regulations:

ASTM F963 + 16 CFR Flammability Test  
16 CFR 1303 Total Lead Content  
ASTM F963 + 16 CFR Physical and Mechanical Test  
ASTM F 963 Soluble Heavy Metal Content  
Total Lead in substrate per CPSIA 2008 (H.R. 4040)  
Total Phthalates Content Test per CPSIA 2008 (H.R. 4040)

III. This product was imported by:

Mary Meyer Corp.  
Route 30  
Townshend, VT 05353 USA  
Tel (+852)-3580-0773

IV. Testing and compliance records are maintained by:

Hong Kong:  
Mary Meyer (Hong Kong) Limited  
11/F, Flat A, Siu On Commercial Building  
243-245 Des Voeux Rd. West  
Hong Kong, S.A.R. Peoples' Republic of China  
Tel: (+852)-2915-2506  
Email: compliance@marymeyer.com  
Attn: Jeffrey Blauner

USA:  
Mary Meyer Corp.  
P.O. Box 275  
Townshend, VT 05353  
USA  
Tel: (802)-365-7793  
email: compliance@marymeyer.com  
Attn: Vikki Dunn

V. This product was manufactured in:

Dongguan, Guangdong Province, Peoples' Republic of China  
November, 2009

VI. The product covered by this certificate was tested for compliance:

Shenzhen, Guangdong Province, Peoples' Republic of China  
November 2009

VII. Third party testing was conducted by:

Specialized Technology Resources (Shanghai) Ltd, Shenzhen Branch  
8 Langshan 2<sup>nd</sup> Road  
North Hi-Tech Industrial Park, Nanshan District  
Shenzhen 518057  
Guangdong Province, Peoples' Republic of China  
(+86)-755-2601-8600

Mary Meyer Corp.  
P.O. Box 275, Route 30  
Townshend, VT 05353 USA  
Tel: (802)-365-7793 Fax: (802)-365-4233